



135770

No.	Description	Tightening torque (N.m)
(1)	Shock absorber bolt on rear axle	105
(2)	Shock absorber bolt on body	62
(3)	Rubber bearing nut	125
(4)	Rear axle bolt on body	105



143846

No.	Description	Tightening torque (N.m)
(5)	Hub carrier bolt	185
(6)	Hub nut	280



143846

No.	Description	Tightening torque (N.m)
(5)	Hub carrier bolt	185
(6)	Hub nut	220



Repair-13x02x05-02x62-1-23-1.xml



XSL version : 3.02 du 22/07/11